



J12
HSK1

+5V J6

J5 -15V

+15V J4

U1

>>> +5V >>>

>> +15V >>>

>>> +3,3V >>>

<<< -15V <<<

J2

F4

R38

R39

R25

J9

R33

R34

F3

J3

R28

R27

R26 R38 R37 R36 R35

W1b Btk Ext to Bot

Top IN1 IN1 to B

J1

J3

3

2