

376.090

## Bauteileliste

SEITE 1

ANZ	GRP	WERT	BAUFORM	HERSTELLER	BEST.-NR.	BEMERKUNG	BENENNUNG
1							0
1	C	4.7nF	C320	UNION CARB.	11329	-	C9
1	C	10nF	C320	UNION CARB.	11307	-	C4
12	C	100nF	C320	UNION CARB.	11096	-	C5,6,7,8,10,11,13,14,16,18,23,25
4	C	100nF	MKS-4	WIMA	11018	-	C15,17,19,26
2	C	150nF	C320	UNION CARB.	11310	-	C29,30
1	C	220nF	C320	UNION CARB.	11311	-	C27
4	C	1uF	C330	UNION CARB.	11313	-	C1,2,3,28
3	C	22uF	SU-R 22/63	PANASONIC	11241	ST.	C12,20,21
9	D	1N4151	DO-35	ITT	13001	-	DB,5,7,7,6,4,3,2,1
3	F	DIL 14	BU..0Z	CAB	13322	-	IC-SOCKEL,
1	F	DIL 24	BU..0Z	CAB	13134	-	IC-SOCKEL
3	F	DIL 16	BU..0Z	CAB	13323	-	IC-SOCKEL,
3	F	DIL 8	BU..0Z	CAB	13137	-	IC-SOCKEL,
1	G	BTE/3HE	KM 6	APRA	ZUKAUF	-	KASSETTE
1	IC	CD 4001	DIL 14	RCA	13233	-	IC6
3	IC	MC14516	DIL 16	MOTOROLA	13259	-	IC2,3,4
2	IC	MAX420CPA	N 8	MAXIM	ZUKAUF	-	IC9,10
1	IC	CD 4047 A	DIL 14	RCA	13250	-	IC5
1	IC	uA 714 HC	TD 99	FAIRCHILD	13399	= DP 07	IC8
1	IC	DAC800CBI	DIL 24	BURR BROWN	13281	-V	IC1
1	IC	LM 339 N	DIL 14	NS	ZUKAUF	-	IC7
6	LP	-	-	VERD	16009	f. RV2	LSP,
5	LP	-	-	VERD	16009	-	TP1,2,3,4,5
2	M	-	AD12	CONTELEC	10496	-	FP-HALTER,
1	PL	FP376090	-	-	-	-	PLATINE
2	R	100R	MBB207-50-BX	BEYSCHLAG	10025	-	R19,24
1	R	220R	MBB207-50-BX	BEYSCHLAG	10033	-	R2
5	R	1K	MBB207-50-BX	BEYSCHLAG	10047	-	R5,6,11,12,16
1	R	2K	MBB207-50-BX	BEYSCHLAG	10054	-	R34
2	R	2K2	MBB207-50-BX	BEYSCHLAG	10055	-	R26,27
8	R	10K	MBB207-50-BX	BEYSCHLAG	10071	-	R7,8,9,13,14,15,22,36
3	R	22K	MBB207-50-BX	BEYSCHLAG	10079	-	R10,21,25
1	R	27K	MBB207-50-BX	BEYSCHLAG	10081	-	R3
1	R	39K	MBB207-50-BX	BEYSCHLAG	10085	-	R1
4	R	100K	MBB207-50-BX	BEYSCHLAG	10094	-	R20,23,28,29
1	R	220K	MBB207-50-BX	BEYSCHLAG	10098	-	R4
2	R	470K	MBB207-50-BX	BEYSCHLAG	10102	-	R17,18
3	R	1M	MBB207-50-BX	BEYSCHLAG	10111	-	R32,33,35
2	R	4M7	MBB207-50-BX	BEYSCHLAG	10114	-	R30,31
1	RL	DIL	281-5-UMD	281-5-UMD	15278	-	REL1

5.36k für ESE!